



# RUSSIAN INTERIM REPORT DETAILS LAST MOMENTS OF FLYDUBAI BOEING 737 CRASH AT ROSTOV

News / Airlines



## Reconstruction of the aircraft (IAC)

**The Russian Interstate Aviation Committee published an interim report, detailing the progress of their investigation into the cause of the fatal accident involving the flydubai Boeing 737-800 at Rostov Airport on March 19.**

The aircraft operated on flight FZ981 from Dubai to Rostov. The flight to Rostov was unevenful. At 22:42 UTC (01:42 local time) in the course of the initial approach at a height of 340 meters (1115 feet), the flight received a windshear alert. The flight crew decided to go around and then continued to a holding pattern waiting for improved weather conditions.

The flight left the holding pattern at 00:28 UTC (03:28 LT) and descended towards Rostov for another attempted approach to runway 22.

As the crew were proceeding with another manual approach, they decided to go around again at a height of 220 meters (721 feet), 4,5 km before the runway. They initiated a climb with a vertical speed of up to 20 m/s (3937 ft/min) and setting the engines to maximum takeoff/go-around

(TOGA) thrust.

One of the probable causes of the go-around decision could have been the 20-knot increase of indicated speed to as much as 176 knots within 3 seconds, which might have been an indication of a windshear.

In the course of the go-around the crew set the flaps to 15° and retracted the landing gear. At the height of 1900 ft (approx. 600 m) after reaching the pitch angle of 18° the pilot flying pushed on the control column, which led to a decrease in vertical acceleration of up to 0.5, increase in forward speed and, consequently, automatic retraction of flaps from 15° to 10° at a speed of over 200 knots.

The short-term decrease in engine thrust within 3 seconds resulted in decreasing speed and flaps extension to 15°, although the following crew inputs to regain maximum takeoff/go-around thrust led to speed increase and reiterated automatic flaps retraction to 10°. The flaps remained in the latter configuration until the impact.

The pilot flying, by pulling up the control column, continued climbing with a vertical speed of as much as 16 m/s (3150 ft/m).

At a height of 900 m there was a simultaneous control column nose down input and stabilizer nose down deflection from -2,5 deg (6,5 units) to +2,5 deg (1,5 units). The FDR recorded a nose down stabilizer input from the stabilizer trim switch of the control wheel lasting 12 seconds, while the CVR record contains a specific noise of rotation of the trim wheels located on both sides of the central pedestal. As a result the aircraft, having climbed to about 1000 m, turned into descent with a negative vertical acceleration of -1g. The following crew recovery actions did not allow to avoid an impact with the ground.

The aircraft hit the runway about 120 m from the threshold with a speed of over 600 km/h and over 50 degrees nose down pitch.

IAC recommends among others to give pilots additional training on elements of go-arounds in various conditions, in manual control mode with two engines operative from various heights and with insignificant flight weights.

investigating agency: Interstate Aviation Committee (IAC / MAK) – Russia   
report status: Interim  
report number: interim report  
report released: 20 April 2016  
duration of investigation: 32 days (1 months)

download report:  [interim report](#)

22 APRIL 2016

SOURCE: AVIATION SAFETY

ARTICLE LINK:

<https://50skyshades.com/index.php/news/airlines/russian-interim-report-details-last-moments-of-flydubai-boeing-737-crash-at-rostov>