



INCIDENT: AUSTRIAN F100 AT STUTTGART ON OCT. 8, 2015, COULD NOT RETRACT ALL GEARS

News / Airlines



Copyright © mau947

For more photos visit <http://www.plane-mad.com/mau947/photos/>

An Austrian [Airlines](#) Fokker 100, registration OE-LVB performing flight OS-184 from Stuttgart (Germany) to Vienna (Austria), was climbing out of Stuttgart's runway 25 when the crew stopped the climb at FL140 and returned to Stuttgart for a safe landing on runway 25 about 25 minutes after departure.

A ground witness reported the aircraft climbed out with the left and nose gear retracting, the right main gear remained extended however. Later the aircraft returned with all gear down for an eventless landing.

11 OCTOBER 2015

SOURCE: THE AVIATION HERALD

ARTICLE LINK:

<https://50skyshades.com/index.php/news/airlines/incident-austrian-f100-at-stuttgart-on-oct-8-2015-could-not-retract-all-gears>